

HI FLUFF X

(FLUFF REMOVER)

APPLICATION:	For removal of fluff loose fibers, threads, Dirt etc. from cotton fabrics before printing.
PROPERTIES:	Tacky surface, capable of picking up Loose fibres, threads, Fluff, pollen material of fabrics till 2000 meters cloth
PHYSICAL STATE & COLOR:	Semi liquid, pourable, white in color
DIRECTION OF USE:	If dilution is required then use water apply HI FLUFF X on to rotary screen while using a brush, Dry in oven for 10 to 20 minutes at 100° C when tackiness disappers after long use in service, apply coat of FLUFF X on top of the ole coat of fluff on top of the oil coat clean brush in butyl acetate.
STORAGE:	12 months
PACKING:	50 Kgs H.D.P.E. carboy